

1313 VENTILATION:


The ventilation was provided by a window which appeared adequate.

**1314 CABINETS/
TOPS:**

The cabinet(s)/ counter(s) were serviceable.

**1315 SINK/
PLUMBING:**

The faucet(s), sink(s) and piping were serviceable with exceptions noted.
a. [CR] Active leaks/corrosion were noted at the water supply piping/shutoff valves. We recommend correcting the condition(s) noted.
b. [CR] There was low water flow from the faucet. We recommend correcting the condition(s) noted.



1316 TOILETS:

The toilet(s) functioned, no leakage noted.

1325 MEDICINE:

The medicine cabinet(s) were serviceable.

1326 MIRRORS:

The mirror(s) were serviceable.

MASTER BATH:

**1301 WALLS/
CEILING:**

[CR] Moisture/stains and damage were noted on the wall. The area tested wet during the inspection. We recommend locating correcting the source as well as any damaged materials.



**1302 CARPET
FLOOR:**

[CR] Moisture/stains and damage were noted on the carpet, tack strip and sub-flooring. The area tested wet during the inspection. We recommend locating and correcting the source as well as any damaged materials.

